FORM MR-AR (Revised 12/2009)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

SMALL MINING OPERATIONS 2009 PROGRESS REPORT January 1, 2009 to December 31, 2009

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

	1.	Mine Permit Number: S/001/0074
	2.	Mine Name: Maria Pit Overburden Dump Pile
	3.	Name of Operator/Permittee: Gene Henrie, dba Quality Crushing
		Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/MINES/Minerals_Related/FORMS/MR-REV-SMO_EXP.pdf .
	4.	Mine Location: SE1/4NW1/4; NE1/4SW1/4, Sec. 22, T27S R11W
	5.	Report the gross amount of ore mined and waste moved, as well as the current disposition of the material (sold, stockpiled, regraded, etc.):
		Gross Ore Mined
		Waste Material Moved 55,000 Tons, oryd ³
		New Disturbance 2.5 Acres during 2009 Area Reclaimed 2.5 Acres during 2009
		Area Reclaimed ————————————————————————————————————
		Total Disturbed Area Acres*
		*Total life of mine disturbance to the end of 2009. Was the ore shipped off site? If not, where is the ore located? Road base only
		was the ore shipped off site? If not, where is the ore located?
		was produced from the overburden dump site.
		Where is the waste located? 47,000K tons were used on roadways.
		8,000K remains on the overburden dump.
	6.	Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE (https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf) for an application for full or partial bond/site release). A D-8 Cat was used to round off the highwalls of the disturbed area. The original road to and from the overburden pile was an existing lopop road and still remains in place.
correct		by certify, under penalties of law, the information provided in this report is true and best of my knowledge and belief.
COLLEC	to the	
		Name (Typed or Print): Gene Henrie, dba Quality Crushing
		Title of Operator: Owner
		Signature of Operator:
		Date: 2/24/10
pb		

-1-

O:\FORMS\reports\MR-AR-SMO2008.doc

RECEIVED